From: GT700@dnvps.com [mailto:GT700@dnvps.com]

Sent: Friday, July 12, 2013 3:30 PM

To: tec-fpmc@fpg.com.tw

Cc: FPMC28 - Data (G Mail); FPMC 28 Vessel Control Group; albert@fpg.com.tw

Subject: FPMC 28, FUEL ANALYSIS REPORT, BALBOA, 28-JUN-2013, SAMPLE: HOU1317119 - NOTE:

SULFUR ABOVE 1.00%

To: FORMOSA PLASTICS MARINE CORPORATION

Attn: Mr SU WEI-CHIH

Attn: Albert

Cc: The Master Of 'FPMC 28'

Attn: Chief Engineer

Cc: V.SHIPS (ASIA) PTE LTD Attn: Vessel Control Group

DNV Petroleum Services - Fuel Analysis Report dated: 12-Jul-2013

Vessel: FPMC 28 (9528378)

Sample Number HOU1317119

Product Type (HFO)
Bunker Port BALBOA
Bunker Date 28-Jun-2013
Sampling Point SHIP MANIFOLD
Sampling Method CONTINUOUS DRIP

Sent From PANAMA CITY, PANAMA Date Sent 09-Jul-2013

Arrived at Lab
Supplier
BP
Loaded From
VAALS
Quantity per C.Eng.
400

Seal Data DNVPS, SEAL INTACT, 7366889

Related Samples

Supplier 7366890 Ship 7366891

SHIP MARPOL 7366892 MARPOL 150451

Receipt Data Unit

 Source Of Data
 B.D.N

 Density @ 15°C
 kg/m³ 989.6

 Viscosity @ 50°C
 mm²/s 360.0

 Sulfur
 % m/m 1.00

 Volume @ 60°F
 bbl 2547.310

 Quantity
 MT 400.183

Test Parameter	Unit	Result	RMG3	80
Density @ 15°C	kg/m³	988.7	991.	.0
Viscosity @ 50°C	mm²/s	359.0	380	0.0
Water	% V/V	0.2	0.5	
Micro Carbon Resi	due % n	n/m	12	18
Sulfur	% m/m	1.09	3.50	
Total Sediment Pot	ential % m	/m LT (	0.01	0.10
Ash	% m/m	0.04	0.15	
Vanadium	mg/kg	47	300	
Sodium	mg/kg	19		
Aluminium	mg/kg	23		
Silicon	mg/kg	22		
Iron	mg/kg	17		
Nickel	mg/kg	27		
Calcium	mg/kg	16		
Magnesium	mg/kg	2		
Zinc	mg/kg	1		
Phosphorus	mg/kg	1		
Potassium	mg/kg	LT 1		
Pour Point	°C I	T 24	30	
Flash Point	°C (	GT 70	60	

### Calculated Values

Aluminium + Silicon mg/kg 45
Net Specific Energy MJ/kg 40.79
CCAI (Ignition Quality) - 850
Quantity (Weight) MT 399.816
Quantity Difference MT -0.367

#### Note:

LT means Less Than, GT means Greater Than. Quantity (Weight) is based on BDN Volume, DNVPS Density and a weight factor of 1.1 kg/m³ (ASTM D1250-80 Table 56).

## Specification Comparison:

Results compared with amended ISO 8217:2005 specification RMG380, table 2. Based on this sample the specification is met.

80

Note: Sulfur has been retested and confirmed.

## Operational Advice:

Approximate fuel temperatures:

# Injection:

140°C for 10 mm<sup>2</sup>/s

125°C for 15 mm<sup>2</sup>/s

 $115^{\circ}C$  for  $20 \text{ mm}^2/\text{s}$ 

110°C for 25 mm<sup>2</sup>/s

Transfer: 45°C

Sulfur - Based on this commercial sample and the sulfur content specified on the BDN, the fuel oil is potentially non-compliant if used within a designated Emission Control Area (ECA, ref. MARPOL Annex VI Reg. 14(4)). It is recommended that the situation is recorded through a notification or Note of Protest (NoP) issued by the Master. Only the relevant official authorities can then advise on any further action necessary. Please note that the official MARPOL sample provided by the supplier is the governing sample regarding the compliance with this statutory requirement. For assistance issuing the Note of Protest, please refer to DNVPS' Instruction Manual.

Fuel contains abrasive contaminants as indicated by Aluminium + Silicon. Efficient centrifuging of the fuel is most important in order to reduce the abrasive contaminant to an acceptable level.

Maintain fuel temperature at 98°C at separator inlet and use reduced flow rate. Consider to operate separators in parallel. Please refer to manufacturers instructions for further information.

Based on Aluminium + Silicon content, we recommend to send a set of FSC samples to assess the efficiency and confirm optimum operation of the fuel treatment plant. As a minimum, representative samples taken before and after the separators are required for this assessment. Red labels should be used for the FSC samples. Please refer to the Instruction Manual included in the sample kits for more detailed information.

Best Regards, On behalf of DNV Petroleum Services Pte Ltd Qamar Hussain Technical Advisor

End of Report for FPMC 28

Reference to part(s) of this report which may lead to misinterpretation is prohibited.

NOTE: Please note that our lab in Oslo is no longer in operation. The latest revision(revision 25, November 2012) of our Air Courier Directory contains instructions on which lab samples should be sent to. Reporting may be delayed for samples that from now on arrive in Oslo. If you have any questions or do not have the latest version of the air courier directory onboard, please contact your nearest DNVPS office.

For technical or operational advice or further information on this report please contact your nearest DNVPS office or contact us directly at

Tel : +1 (281) 470 1030 Email : <u>Houston@dnvps.com</u>